

2026 Acura MDX

Stock: X19614
VIN: 5J8YE1H38TL020736



IMAGE COMING SOON

Internet Price	\$49,825
Doc Fee	\$175
Final Price	\$50,000



 6098 miles	 X19614	 3.5L V6 Cylinder Engine	 MPG: 19 City - 25 Hwy
 10-Speed A/T	 awd		

VEHICLE DETAILS

 Rear Spoiler	 AWD	 Bluetooth	 3rd Row Seat	 Heated Seats
 Navigation	 Rear View Cameras	 Wi-Fi Hotspot	 Apple CarPlay	 Power Liftgate
 Remote Trunk Release	 Child Safety Locks	 Engine Immobilizer	 Tire Pressure Monitor	 Universal Garage Door Opener
 Blind Spot Detection	 Collision Braking Assist	 Keyless Start	 Keyless Entry	 Distance Pacing Cruise Control
 Power Door Locks	 Cross Traffic Alert	 Security System	 Automatic Headlights	

09/02/2026 05:25

/inventory/used/acura/mdx/used-2026-acura-mdx-in-bay-shore-ny-5j8ye1h38tl020736

CALL US:
SALES: (631) 658-4848

Sales Hours
Mon - Thu: 09:00am - 09:00pm
Fri: 09:00am - 07:00pm
Sat: 09:00am - 06:00pm
Sun: 11:00am - 04:00pm

2026 Acura MDX

Stock: X19614
VIN: 5J8YE1H38TL020736

Comments

CARFAX 1-Owner. EPA 25 MPG Hwy/19 MPG City! Liquid Carbon Metallic exterior and Ebony interior, MDX trim. CLICK ME!
KEY FEATURES INCLUDE
Third Row Seat, Navigation, Moonroof, Panoramic Roof, All Wheel Drive, Power Liftgate, Rear Air, Heated Driver Seat, Back-Up Camera, iPod/MP3 Input, Onboard Communications System, Aluminum Wheels, Keyless Start, Dual Zone A/C, WiFi Hotspot. Rear Spoiler, MP3 Player, Keyless Entry, Remote Trunk Release, Privacy Glass. CARFAX 1-Owner Acura MDX with Liquid Carbon Metallic exterior and Ebony interior features a V6 Cylinder Engine with 290 HP at 6200 RPM*.
MORE ABOUT US
Acura of Bay Shore is a prestigious Acura dealer serving both Nassau and Suffolk counties on Long Island With its huge inventory of certified pre-owned cars and SUVs, Acura of Bay Shore is dedicated to providing its customers with unparalleled service and commitment.
*Based on current year EPA mileage ratings. Use for comparison purposes only. Your actual mileage will vary, depending on how you drive and maintain your vehicle, driving conditions, battery pack age/condition (hybrid models only) and other factors.